



CONTACT REPORT

Project Number:

136

Prepared by: StarlinDate: 12/31/85☐ Made Call to:

Contact: _____

☐ Received Call from:

Affiliation: _____

☐ Meeting Held with:

Phone #: () _____

Date: _____

Discussion: Made trip to 1st Ave. Bridge area in Seattle to
locate site of First Ave. Bridge Landfill. Accompanying
diagram shows layout of the area. It is primarily an
industrial area, there were no areas that looked like landfill
sites

USEPA SF



1568493

Distribution:

Seattle Office
Environmental Technology Group
13400-B Northup Way, Suite 38
Bellevue, Washington 98005
(206) 747-7899